

Environmental Protection Agenc

1701 S. First Street Maywood, IL. 60153

312/345-9780

Refer to: Lake County - 09719001 - Waukegan/Municipal #1

March 19, 1981

Ellis Perl, Director Department of Public Works City of Waukegan 146 N. Utica Street Waukegan, Illinois 60085

EPA Region 5 Records Ctr.

Dear Mr. Perl:

A reinspection of your property located at the southwest corner of Yorkhouse and McAree Roads in Waukegan was made by Jeff Stofferahn and Dan Shane, representing this Agency on March 9, 1981.

James Ambroso of the Lake County Health Department was also in attendance during the inspection.

The inspection disclosed the following condition(s) which constitute violations of the Environmental Protection Act and Chapter 7 of the Illinois Pollution Control Board Solid Waste Rules and Regulations:

... Leachate was observed to be seeping from the south and east edges of the filled areas into the perimeter drainage ditches. You should take immediate action to correct this situation.

... Leachate was ponded on the south perimeter drainage ditch. You should take immediate action to correct this violation.

... Access to the site is not restricted. A gate, fencing or other measures should be provided to prevent access to the site from McAree Road.

As per your letter of December 16, 1980, I would be happy to meet with you, at your convenience, and discuss possible corrective action at this site.

Sincerely,

A - Buly

Kenneth P. Bechely, Northern Region Manager Field Operations Section Division of Land/Noise Pollution Control

KPB: JAS: prg

Enclosure: Inspection Report

cc: Division File / Northern Region RECEIVED

MAR 23 1981

E.P.A. - D.L.P.C. STATE OF ILLINO'S



DATE

3/9/31

ENVIRONMENTAL PROTECTION AGENCY STATE OF ILLINOIS INTER-OFFICE CORRESPONDENCE



RECEIVED

MAR 23 1931

	MEMO TO File 097190										9001					EPA - DLFC															
	FROM								UAS						_ STATE OF ILLINO.S																
SUBJECT									nahe						COUNTY — D L P C Inspection																
							· · ·	C	Veuhegen						_ COUNTY - D L P C Inspection																
			GEN	IER/	AL R	EMA	ARK	S .	Inspected s							-	<u> </u>	72,	2	in	د کھے د ک	Li.	ne 1	7	T	<i>E [-</i>	<u>A</u> T	-D	<u>LPC</u> ~/.	·a	nd
								Č	northwest en						trave to to site was upon where																
numerous T													su	suchs were entering and depositing																	
\mathcal{O}													/	og to use surge stochpelo altready present														ul			
INTERVIEW This											1	lay was being worked into the large pile by a												_							
									near the randomly deposited refuse relate previously													J.									
									2	ac	<u> </u>	Te	12	RP	w	was again found at									(A), and The leachate						
								_	w	21	CL	qu	m.	00	noted in the draine								uero alse found								
			DIA	GRA	M			•					_						_			,						-	ل محاوط		
m	1 4		1	10		بيرا	tec	0	<u> </u>	ره	ſ.	, ,	Lea		1 '	,	22	L i				!		(7	1	١	l	2	1	
		-		ر		2		op	س ت ر د			1	200	27		20	777		0	20		ے۔	,	70,	7		رما	7		مد	20-
	ra	in	رمره		de	ZC.		ees	, ,	2	d	24	J	eci		, ,	200	m		2	1	1/6	كورون	رمر ف	مرب	1	cu:	مريد	7	10	
1	מ פי	٠	7	۵.	n	معد	en		7	ده	4	CL	1	Le		ne	2	100	Pec	Lec	te	۷,	0	رمه	212	d					
																			C			Ų	6A	r H	2051	Ē	RØ				
\Box		N-		<u> </u>	_	17																									
_		1								_						CI	U1.		4	ļ						_					_
						\prod				_			ļ						4	_	_	/_	E E	[a	٠,	_					
_							/				Ž	-17	ļ				<u> </u>	(0		r			30	ep.	-						\rightarrow
-										lay	,			_					7	8	<u> </u>				-				\vdash		
											+						 		+	140	-					-			\vdash		\dashv
+	_					-					۲			_					+	1	-			ce	- <	_				\dashv	
				_				-						<u> </u>						1		<u> </u>	- 2		22	177	1	4	\vdash		\dashv
-			-			-													7		-					-		_			\dashv
1	\dashv					-			-			_						٥	+		-						 			\dashv	\dashv
									(A)	w	100		270	=	م	SR	×	01)	+											\dashv	
								O.	~		7								-												
										1ea	cha	e	六		1	ء جو	less	ارع													
											d.	پ د م																			